




SIZE CHART - MENS JERSEYS

MENS - Body Measurements

SIZES		XS	S	M	L	XL	XXL	XXXL	4XL
CHEST	"	34	36	38	40	42	45	48	51
	cm	85	90	95	100	105	112	120	129
WAIST	"	28	30	32	34	36	39	42	45
	cm	70	75	80	85	90	97	105	113

How to measure garment - Measurements are taken with garment relaxed

- A Chest circumference measured relaxed at underarm
- B Hem circumference measured relaxed
- C To find waist measure 46cm from front bottom collar. Measure waist circumference relaxed at this level
- D Back length from bottom collar to hem



FIT SYMBOL

ATHLETIC FIT

MENS KZG - Relaxed Garment Measurements



	SIZE		XS	S	M	L	XL	2XL	3XL	4XL
A	CHEST CIRCUMFERENCE	cm	91	96	101	106	111	119	126	134
B	ELASTICATED HEM CIRCUMFERENC	cm	70	75	80	85	90	98	105	113
C	WAIST CIRCUMFERENCE	cm	77	82	87	92	97	105	112	120
D	BACK LENGTH:Bottom collar to hem	cm	65	66	67	68	69	71	72	74

Disclaimer: This is an approximate guideline and reasonable tolerances for manufacturing is to be allowed.

